



INSPECTION REPORT

**S W FOUNDATION FOR
BIOMEDICAL RESEARCH**

P. O. BOX 760549
SAN ANTONIO, TX 78245 0549

Customer ID: 1512

Certificate: 74-R-0003

Site: 001

MILITARY DR. LOOP 410

Inspection

Type: ROUTINE INSPECTION

Date: JUL-15-2003

All redactions on this page are pursuant to (b)(6) & (b)(7)(c).

3.76 (c)

HOUSING FACILITIES, GENERAL.

The surfaces of housing facilities must be constructed of materials which allow them to be readily cleaned and sanitized. The surfaces must be maintained in good repair.

The walls in the hospital ward have paint which has chipped. This makes it difficult to sanitize the room properly. There are areas by the air vent where the wall board is broken and sagging due to water leakage. This area can not be properly cleaned. The wall board which has been damaged by water may provide an environment for growth of mold which may lead to health problems for the animals.

The surfaces and area by the air vents in the room need to be repaired and maintained so they may be properly cleaned. Correct By: 8-15-03

3.77 (c)

SHELTERED HOUSING FACILITIES.

The sheltered part of of sheltered housing facilities must be lighted well enough to permit routine inspection, cleaning and observation of the non human primates.

The light fixtures are old in this facility and some have broken when the bulbs have been changed. The lighting in the facility will not be adequate when the side walls are down in cool weather.

The light fixtures in the facility need to be repaired or replaced to provide adequate lighting for routine husbandry procedures. Correct By: 8-15-03

Inspection was conducted with [redacted] Bill Atkins, Animal Care Supervisor and Dr. Pannill-USDA-Animal Ca

Prepared By: Elizabeth Pannill omvms
ELIZABETH PANNILL, V. M. O., USDA, APHIS, Animal Care

Title: VETERINARY MEDICAL OFFICER, Inspector ID: 4018

Date:
JUL-15-2003

Received By: [redacted]

Title: [redacted]

Date:
JUL-15-2003