



INSPECTION REPORT

**SOUTHWEST FOUNDATION FOR
BIOMEDICAL RESEARCH**

Customer ID: 1512
Certificate: 74-R-0003

P. O. BOX 760549
SAN ANTONIO, TX 78245 0849

Site: 001
MILITARY DR LOOP 410

Inspection
Type: ROUTINE INSPECTION
Date: JUL-21-2005

All redactions on this page are pursuant to (b)(6) & (b)(7)(c).

- 3.75 (a)
- 3.75 (b)
- 3.75 (c)

HOUSING FACILITIES, GENERAL.

a) Structure: construction. Housing facilities for nonhuman primates must be designed and constructed so that they are structurally sound for the species of nonhuman primates housed in them. They must be kept in good repair, and they must protect the animals from injury, contain the animals securely, and restrict other animals from entering.

The chain link fencing is in need of repair in several of the baboon enclosures. The chain link fencing has been patched but there are gaps and the fence is weak in the patched areas. Problems with the fencing were noted in these enclosures: B 3, B 4, C-8, D-16 and the alley way of the D enclosures. The fencing needs to be repaired and maintained in good condition to prevent escape or injury of the non human primates: Correct By: 8-21-05

The roof is leaking in several areas of the facility. Water from recent rains is a problem in the following areas: NICU: Front room has one area where the floor was wet and a trash can was being used to collect water from the ceiling. Building 6 Back Hall: There is standing water on the floor next to the wall. The molding against the ceiling is beginning to rot due to water leaking from the roof. These areas need to be repaired to prevent mold and structural damage from developing. Correct By: 8-21-05

(b) Condition and site. Housing facilities and areas used for storing animal food or bedding must be free of any accumulation of trash, waste material, junk, weeds, and other discarded materials. A large pile of discarded metal, broken windows and discarded materials has accumulated behind the cage storage area. This trash pile is a breeding ground for rodents and other pests and needs to remove. Correct By: 8-21-05

Surfaces shall be maintained in good repair. Building 23/24 : the flooring in the outside cage wash area has eroded and cannot be properly sanitized due to the uneven surface. This area needs to be repaired so proper husbandry may be conducted. Correct By: 8-21-05

Inspection was conducted 7/19/05 - 7/21/05 with [redacted] and Dr. Pannill USDA

Prepared By: Elizabeth Pannill
ELIZABETH PANNILL, V.M.O., USDA, APHIS, Animal Care

Title: VETERINARY MEDICAL OFFICER Inspector ID: 4018

Date:
JUL-21-2005

Received By: [redacted]
Title: [redacted]

Date:
JUL-21-2005



1512 cust_id

154852 insp_id

28057 site_id

INSPECTION REPORT

**SOUTHWEST FOUNDATION FOR
BIOMEDICAL RESEARCH**

Customer ID: 1512

Certificate: 74-R-0003

Site: 002

BROOKS AFB

P. O. BOX 788549
SAN ANTONIO, TX 78248 0549

Inspection

Type: ROUTINE INSPECTION

Date: JUL-21-2005

No non compliant items identified this date.

Prepared By:

Elizabeth Pannill

ELIZABETH PANNILL, V.M.O. , USDA, APHIS, Animal Care

Title: VETERINARY MEDICAL OFFICER Inspector ID: 4018

Date:

JUL-21-2005

Received By:

(b)(6), (b)(7)c

Date:

JUL-21-2005

Title: