



1512 cust_id

154588 insp_id

4564 site_id

INSPECTION REPORT

**SOUTHWEST FOUNDATION FOR
BIOMEDICAL RESEARCH**

Customer ID: 1512

Certificate: 74-R-0003

Site: 001

MILITARY DR LOOP 410

P. O. BOX 780549
SAN ANTONIO, TX 78245 0549

Inspection

Type: ROUTINE INSPECTION

Date: JUL-02-2004

All redactions on this page are pursuant to (b)(6) & (b)(7)(c).

3.75 (f)

HOUSING FACILITIES, GENERAL.

Housing facilities must be equipped with disposal facilities and drainage systems that are constructed and operated so that animal wastes and water are rapidly eliminated and the animals stay dry .

During heavy rain there is a drainage problem in the chimp condos . The sewer system is backing up into some of the chimp huts . A plan has been developed to enlarge the system which would prevent this problem but work has not yet been completed. The Regional Office in Ft Collins shall be notified of the expected completion date for the sewer upgrade project .

CORRECT BY : 8-2-04

NOTE : This non compliant item was left out of the narrative dated 7-1-04 . Inspection of the chimp area was on 6-29-04 and conducted with [redacted] and Drs. Pannill & Kjos -USDA Animal Care .

Prepared By: Elizabeth Pannill V.M.O.

ELIZABETH-PANNILL, V.M.O. , USDA, APHIS, Animal Care

Title: VETERINARY MEDICAL OFFICER, Inspector ID: 4018

Date:
JUL-02-2004

Received By: [redacted]

Title: [redacted]

Date:
JUL-02-2004

JUL 15 2004



INSPECTION REPORT

1512 cust_id
154587 insp_id
29057 site_id

**SOUTHWEST FOUNDATION FOR
BIOMEDICAL RESEARCH**

Customer ID: 1512
Certificate: 74-R-0003

Site: 002
BROOKS AFB

P. O. BOX 780549
SAN ANTONIO, TX 78245 0549

Inspection
Type: ROUTINE INSPECTION
Date: JUL-02-2004

All redactions on this page are pursuant to (b)(6) & (b)(7)(c).

3.75 (c)

HOUSING FACILITIES, GENERAL.

Surfaces shall be maintained in good repair .

Due to recent heavy rains the roof has leaked causing damage to one section of the ceiling in the hospital ward . The ceiling and roof need to be repaired.

CORRECT BY : 8-2-04

Inspection was conducted with [redacted] Bill Atkins and Dr. Pannill- USDA-Animal Care

Prepared By: Elizabeth Pannill DVM MS
ELIZABETH PANNILL, V.M.O. , USDA, APHIS, Animal Care

Title: VETERINARY MEDICAL OFFICER , Inspector ID: 4018

Date:
JUL-02-2004

Received By: [redacted]
Title: [redacted]

Date:
JUL-02-2004



INSPECTION REPORT

1512 cust_id
154587 insp_id
29057 site_id

**SOUTHWEST FOUNDATION FOR
BIOMEDICAL RESEARCH**

Customer ID: 1512

Certificate: 74-R-0003

Site: 002

BROOKS AFB

Inspection

Type: ROUTINE INSPECTION

Date: JUL-02-2004

P. O. BOX 780549
SAN ANTONIO, TX 78245 0549

All redactions on this page are pursuant to (b)(6) & (b)(7)(c).

3.75 (c)

HOUSING FACILITIES, GENERAL

Surfaces shall be maintained in good repair .

Due to recent heavy rains the roof has leaked causing damage to one section of the ceiling in the hospital ward . The ceiling and roof need to be repaired.

CORRECT BY : 8-2-04

Inspection was conducted with SWFBR manager [redacted] Bill Atkins and Dr. Pannill- USDA-Animal Care

Prepared By: Elizabeth Pannill V.M.O.
ELIZABETH PANNILL, V.M.O. , USDA, APHIS, Animal Care

Title: VETERINARY MEDICAL OFFICER Inspector ID: 4018

Date:
JUL-02-2004

Received By: [redacted]
Title: [redacted]

Date:
JUL-02-2004

JUL 15 2004